

xTool F2 Ultra UV

294 x 429 mm | 11.57 x 16.89 in | A4

MXF-K007-001 body only; no controller or conveyor

- 1. Print this page first: Actual size / 100%, single-sided, one page per sheet. No Fit or Shrink.
- 2. Measure both axes of the 50 mm square and the 100 mm bar below. If wrong, fix scaling.
- 3. Print all tiles with the SAME settings. Check each tile's 50 mm bar. Trim dashed borders.
- 4. Match row/column labels. Butt tile edges with NO gap or overlap; tape from behind.
- 5. Measure the assembled dark rectangle: 294 x 429 mm. Do not measure the tile borders.

ASSEMBLY MAP (NOT TO SCALE)

R1C1	R1C2
R2C1	R2C2

2 columns x 2 rows


4 tiles + this guide

Dashed: trim border

Heavy solid: machine body

Light grid: 50 mm spacing

CALIBRATION / MEASURE BEFORE ASSEMBLING



100 mm between end ticks



Next: check your room

laserroomready.com


Scan for this machine's checker

Source checked 2026-09-16: <https://support.xtool.com/article/2595>


Planning rectangle from product dimensions. No feet, lid travel, service, hose or accessory space.


Organizational aid, not engineering, safety approval or code certification. Remove paper before use.

Original layout: LaserRoomReady, CC BY 4.0. Preserve source/date/limits. Not endorsed by xTool.




Trim dashed border. Butt edges, no overlap. 5 mm outer padding is NOT clearance.





Trim dashed border. Butt edges, no overlap. 5 mm outer padding is NOT clearance.



Trim dashed border. Butt edges, no overlap. 5 mm outer padding is NOT clearance.